




Pebble Steel Vibration Motor Replacement

This is a guide to replace the vibration motor in a Pebble Steel Smartwatch.

Written By: Orlandria Heggs




INTRODUCTION

Is your Pebble Steel not vibrating properly? Replacing the vibration motor may solve this problem.

TOOLS:

- [T3 Torx Screwdriver](#) (1)
 - [Tweezers](#) (1)
 - [iFixit Opening Tools](#) (1)
-

Step 1 — Internal Hardware




- Use a Torx T3 screwdriver to unscrew the four 3.5 mm Torx T3 screws holding the back plate.
- ☑ Make sure the screws are kept in a safe place to insure they are not lost.
- Remove the back plate.

Step 2




- Use a pair of tweezers to grab onto the black plastic frame and remove the internal hardware.
- ⓘ Adhesive on the back side of the battery holds the internal components to the front case.
- Use tweezers or a plastic opening tool to disconnect the ribbon cable from the motherboard.

Step 3 — Vibration Motor



- Use a small plastic opening tool to remove the vibration motor from the motherboard.

Step 4



- Use a pair of tweezers to detach both the blue and red wires from the motherboard.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-26 08:46:15 AM.